TCS Green Mounted Stones /

E Solo Gree Bitem #4501-1 Safety Data (

Safety Data Sheet

Prepared according to Federal Register / Vol. 77, No. 58 / Friday, May 15, 2015 / Rules and Regulations Revision date: 05/15/2015 Version: 1.0

SECTION 1: Identification of the substance/mixture and of the company/undertaking

Product identifier 1.1.

Product name	: TCS Green Mounted Stones
Product form	: Vitrified bonded stone
Other means of identification	: Grinding tools
1.2. Relevant identified uses of	the substance or mixture and uses advised against
Use of the substance/mixture	: Abrasive materials used for grinding removable dental appliances

1.3. Details of the supplier of the safety data sheet

Thermoplastic Comfort Systems, Inc 2619 Lime Ave. Signal Hill, CA 90755 (562)-426-2970

1.4. **Emergency telephone number**

No additional information available

SECTION 2: Hazards identification

Classification of the substance or mixture 2.1.

GHS-US classification

Not classified

Label elements 22

GHS-US labelling

No labelling applicable

2.3. Other hazards

No additional information available

Unknown acute toxicity (GHS-US) 2.4.

No data available

SECTION 3: Composition/information on ingredients

3.1. Composition:

Aluminum Oxide (AL2O3) or Silicon Carbide (SiC). Non-toxic, class as nuisance dust.

Inert fillers: Feldspar >35%, Pottery stone >20%, Frit >10%, Clay 15%. All the fillers are considered to be non-toxic. Temporary binder: Dextrin, water. Non-toxic.

SECTION 4: First aid measures	
4.1. Description of first aid measures	
First-aid measures after ingestion	: If dust is swallowed seek medical attention.
First-aid measures after inhalation	: If overexposed to dust, remove victim to fresh air and get medical attention.
First-aid measures after eye contact	: IF IN EYES: Immediately flush with plenty of water for at least 5 minutes, holding eyelids open. Remove contact lenses if present and easy to do so. Continue rinsing. Obtain immediate medical attention for foreign body in eye.
First-aid measures after skin contact	: Wash dust from skin with soap and water. Launder contaminated clothing before reuse.
4.2. Indication of any immediate medical attention and special treatment needed No additional information available	

SECT	ON 5: Firefighting measures	
5.1.	Extinguishing media	
Suitable	extinguishing media	: Use any media that is appropriate for the surrounding fire.

05/15/15

Special Fire Fighting Procedure

None needed

Safety Data Sheet Prepared according to Federal Register / Vol. 77, No. 58 / Friday, May 15, 2015 / Rules and Regulations Revision date: 05/15/2015 Version: 1.0

	m the substance or mixture
Fire hazard	: Product is not flammable, however, consideration must be given to the potential fire/explosion hazards from the base material being processed. Many materials create flammable/explosive dusts or turnings when machined or ground.
Explosion hazard	: Product is not explosive.
Reactivity	: No dangerous reactions known under normal conditions of use.
5.3. Advice for firefighters	
Firefighting instructions	: Use water spray or fog for cooling exposed containers. Exercise caution when fighting any chemical fire. Do not dispose of fire-fighting water in the environment. Prevent human exposur to fire, fumes, smoke and products of combustion.
Protection during firefighting	: Do not enter fire area without proper protective equipment, including respiratory protection. Self-contained breathing apparatus.
SECTION 6: Accidental release	se measures
6.1. Personal precautions, prot	ective equipment and emergency procedures
General measures	: No specific emergency measures are required other than good laboratory hygiene and safety practices.
6.1.1. For non-emergency persor	nel
Protective equipment	: Wear Protective equipment as described in Section 8.
6.1.2. For emergency responders	
Protective equipment	: Wear suitable protective clothing, gloves and eye or face protection.
•	s ers. Notify authorities if product enters sewers or public waters. Avoid release to the environment.
	ontainment and cleaning up
For containment	: Pick up, sweep up.
Methods for cleaning up	: Disposal in accordance with local regulations
•	
6.4. Reference to other section	
6.4. Reference to other section	s
6.4. Reference to other section No additional information available	s prage
6.4. Reference to other section No additional information available SECTION 7: Handling and sto	s Drage ing : Use only with adequate ventilation. Avoid breathing dust. Wash thoroughly after handling and
6.4. Reference to other section No additional information available SECTION 7: Handling and sto 7.1. Precautions for safe handl	s Drage ing Use only with adequate ventilation. Avoid breathing dust. Wash thoroughly after handling and use, especially before eating, drinking or smoking. Consider potential exposure to component of the base materials or coatings being machined or ground. Refer to OSHA's substance
6.4. Reference to other section No additional information available SECTION 7: Handling and sto 7.1. Precautions for safe handl Precautions for safe handling	s Drage ing Use only with adequate ventilation. Avoid breathing dust. Wash thoroughly after handling and use, especially before eating, drinking or smoking. Consider potential exposure to component of the base materials or coatings being machined or ground. Refer to OSHA's substance specific standards for additional work practice requirements where applicable. In normal power machining operations, the material being removed will fly off the cutting tool with considerable force. The potential for serious injury exists for both the operator and others in the work area (possibly 50 feet or more from the cutting tool). To protect against this hazard, before rotating the cutting tool, during rotation and until the rotation stops, all persons in the area must wear safety goggles or full face shields over safety glasses with side shields along with appropriate protective clothing.
6.4. Reference to other section No additional information available SECTION 7: Handling and sto 7.1. Precautions for safe handl Precautions for safe handling	s Drage ing Use only with adequate ventilation. Avoid breathing dust. Wash thoroughly after handling and use, especially before eating, drinking or smoking. Consider potential exposure to componen of the base materials or coatings being machined or ground. Refer to OSHA's substance specific standards for additional work practice requirements where applicable. In normal power machining operations, the material being removed will fly off the cutting tool with considerable force. The potential for serious injury exists for both the operator and others in the work area (possibly 50 feet or more from the cutting tool). To protect against this hazard, before rotating the cutting tool, during rotation and until the rotation stops, all persons in the area must wear safety goggles or full face shields over safety glasses with side shields
 6.4. Reference to other section No additional information available SECTION 7: Handling and store 7.1. Precautions for safe handle Precautions for safe handling 7.2. Conditions for safe storage 	s Drage ing Use only with adequate ventilation. Avoid breathing dust. Wash thoroughly after handling and use, especially before eating, drinking or smoking. Consider potential exposure to componen of the base materials or coatings being machined or ground. Refer to OSHA's substance specific standards for additional work practice requirements where applicable. In normal power machining operations, the material being removed will fly off the cutting tool with considerable force. The potential for serious injury exists for both the operator and others in the work area (possibly 50 feet or more from the cutting tool). To protect against this hazard, before rotating the cutting tool, during rotation and until the rotation stops, all persons in the area must wear safety goggles or full face shields over safety glasses with side shields along with appropriate protective clothing. e, including any incompatibilities
 6.4. Reference to other section No additional information available SECTION 7: Handling and store 7.1. Precautions for safe handle Precautions for safe handling 7.2. Conditions for safe storage 	s Drage ing Use only with adequate ventilation. Avoid breathing dust. Wash thoroughly after handling and use, especially before eating, drinking or smoking. Consider potential exposure to component of the base materials or coatings being machined or ground. Refer to OSHA's substance specific standards for additional work practice requirements where applicable. In normal power machining operations, the material being removed will fly off the cutting tool with considerable force. The potential for serious injury exists for both the operator and others in the work area (possibly 50 feet or more from the cutting tool). To protect against this hazard, before rotating the cutting tool, during rotation and until the rotation stops, all persons in the area must wear safety goggles or full face shields over safety glasses with side shields along with appropriate protective clothing. e, including any incompatibilities : Store in a dry location
 6.4. Reference to other section No additional information available SECTION 7: Handling and stor 7.1. Precautions for safe handle Precautions for safe handling 7.2. Conditions for safe storage Storage conditions 	s Drage ing Use only with adequate ventilation. Avoid breathing dust. Wash thoroughly after handling and use, especially before eating, drinking or smoking. Consider potential exposure to componen of the base materials or coatings being machined or ground. Refer to OSHA's substance specific standards for additional work practice requirements where applicable. In normal power machining operations, the material being removed will fly off the cutting tool with considerable force. The potential for serious injury exists for both the operator and others in the work area (possibly 50 feet or more from the cutting tool). To protect against this hazard, before rotating the cutting tool, during rotation and until the rotation stops, all persons in the area must wear safety goggles or full face shields over safety glasses with side shields along with appropriate protective clothing. e, including any incompatibilities : Store in a dry location
 6.4. Reference to other section No additional information available SECTION 7: Handling and store 7.1. Precautions for safe handle Precautions for safe handling 7.2. Conditions for safe storage Storage conditions SECTION 8: Exposure controct 8.1. Exposure Guidelines 	s Drage ing Use only with adequate ventilation. Avoid breathing dust. Wash thoroughly after handling and use, especially before eating, drinking or smoking. Consider potential exposure to componen of the base materials or coatings being machined or ground. Refer to OSHA's substance specific standards for additional work practice requirements where applicable. In normal power machining operations, the material being removed will fly off the cutting tool with considerable force. The potential for serious injury exists for both the operator and others in the work area (possibly 50 feet or more from the cutting tool). To protect against this hazard, before rotating the cutting tool, during rotation and until the rotation stops, all persons in the area must wear safety goggles or full face shields over safety glasses with side shields along with appropriate protective clothing. e, including any incompatibilities : Store in a dry location

Safety Data Sheet

Prepared according to Federal Register / Vol. 77, No. 58 / Friday, May 15, 2015 / Rules and Regulations Revision date: 05/15/2015 Version: 1.0

Personal protective equipment	: Gloves. Protective goggles.
Hand protection	: Use cloth or leather gloves.
Eye protection	: Use eye protection suitable to the environment.
Skin and body protection	: Wear protective clothing as needed to prevent contamination of personal clothing. Hearing protection may be required.
Respiratory protection	: Use NIOSH approved respirator if exposure limits are exceeded or where dust exposures are excessive. Consider the potential for exposure to components of the coatings or base material being machined or ground in selecting proper respiratory protection. Refer to OSHA's specific standards for lead, cadmium, etc. where appropriate. Selection of respiratory protection depends on the contaminant type, form and concentration. Select and use respirators in accordance with OSHA 1910.134 and good industrial hygiene

9.1. Information on basic physical and	chemical properties
Physical state	: Solid
Appearance	: Bur
Color	: Green and metal
Odor	: None
Odor Threshold	: No data available
рН	: No data available
Relative evaporation rate (butylacetate=1)	: No data available
Melting point	: No data available
Freezing point	: No data available
Boiling point	: Not Applicable
Flash point	: No data available
Auto-ignition temperature	: No data available
Decomposition temperature	: No data available
Flammability (solid, gas)	: No data available
Vapour pressure	: Solid
Relative vapour density at 20 °C	: Heavier than air
Relative density	: No data available
Solubility	: Water: Negligible
Log Pow	: No data available
Log Kow	: No data available
Viscosity, kinematic	: Not applicable
Viscosity, dynamic	: Not applicable
Explosive properties	: Not applicable
Oxidising properties	: No data available
Explosive limits	: No data available

9.2. Other information

No additional information available

SECTION 10: Stability and reactivity

10.1. Reactivity

No dangerous reactions known under normal conditions of use.

10.2. Chemical stability

Stable under use and storage conditions as recommended in section 7.

10.3. Possibility of hazardous reactions

None known.

10.4. Conditions to avoid

None known.

Safety Data Sheet

Prepared according to Federal Register / Vol. 77, No. 58 / Friday, May 15, 2015 / Rules and Regulations Revision date: 05/15/2015 Version: 1.0

10.5. Incompatible materials

None known.

10.6. Hazardous decomposition products

Dust from machining could contain ingredients listed in Section 3 and other, potentially more hazardous components of the base material being processes or coatings applied to the base material.

10.7. Hazardous Polymerization:

Will not occur

SECTION 11: Toxicological information

11.1. Information on toxicological effects

HEALTH HAZARDS:

Ingestion: None expected under normal use conditions. Swallowing large pieces may cause obstruction of the gastrointestinal tract.

Inhalation: Dust may cause respiratory irritation.

Eye: Dust may cause eye irritation. Dust particles may cause abrasive injury to the eyes.

Skin: Rubbing product across the skin may cause mechanical irritation or abrasions.

Chronic: Long-term overexposure to respirable dust may cause lung damage (fibrosis) with symptoms of coughing, shortness of breath and diminished breathing capacity. Skin and/or respiratory sensitization may also occur. Chronic effects may be aggravated by smoking. Prolonged exposure to elevated noise levels during operations may affects hearing. A greater hazard, in most cases, is the exposure to the dust/fumes from the material or paint/coatings being processed. Most of the dust generated during machining is from the base material being machined and the potential hazard from this exposure must be evaluated.

Carcinogenicity: No information available

Medical Conditions Aggravated by Exposure: Employees with pre-existing respiratory disease may be at risk from exposure.

Acute Toxicity Values:

This product and its components are not acutely toxic. The only acute toxicity data available for the components are listed below.

SECTION 12: Ecological information

12.1. Toxicity

No additional information available

12.2. Persistence and degradability

No additional information available.

12.3. Bioaccumulative potential

No additional information available

12.4. Mobility in soil

No additional information available

12.5. Other adverse effects

No additional information available

SECTION 13: Disposal considerations

13.1. Dispose in accordance with all applicable local, state/provincial and federal regulations. Local regulations may be more stringent than regional and national requirements. It is the responsibility of the waste generator to determine the toxicity and physical characteristics of the material to determine the proper waste identification and disposal in compliance with applicable regulations.

: No supplementary information available.

SECTION 14: Transport information

In accordance with DOT

Not hazardous for transport

Additional information

Other information

Transport by sea

No additional information available

Air transport

No additional information available

Labels Requires: None

Safety Data Sheet

Prepared according to Federal Register / Vol. 77, No. 58 / Friday, May 15, 2015 / Rules and Regulations Revision date: 05/15/2015 Version: 1.0

SECTION 15: Regulatory information	
15.1. US Federal regulations	
TCS Green Mounted Stones	
SARA Section 311/312 Hazard Classes	None

California Proposition 65: WARNING You create dust when you cut, sand, drill or grind materials such as wood, paint, cement, masonry or metal. This dust often contains chemicals known to cause cancer, birth defects or other reproductive harm.

EPA TSCA Inventory: All of the ingredients in this product are listed on the EPA TSCA Inventory.

Canadian WHMIS Classification: Not a controlled product.

Canadian CEPA: All of the ingredients are listed on the Canadian DSL.

This product has been classified under the CPR and this MSDS discloses information elements required by the CPR.

SECTION 16: Other inform	ation
Indication of changes	: Revision 1.0: New SDS Created.
Revision date	: 05/15/2015
Other information	: Author: MSP.
NFPA health hazard	: 1 - Exposure could cause irritation but only minor residual injury even if no treatment is given.
NFPA fire hazard	: 0 - Materials that will not burn.
NFPA reactivity	: 0 - Normally stable, even under fire exposure conditions, and are not reactive with water.
HMIS III Rating	
Health	: 1
Flammability	: 0
Physical	: 0
Personal Protection	

All information, recommendations and suggestions appearing herein concerning this product are based upon data obtained from the manufacturer and/or recognized technical sources; however, Thermoplastic Comfort System, Inc. makes no warranty, representation or guarantee as to the accuracy, sufficiency, or completeness of the material set forth herein. It is the user's responsibility to determine the safety, toxicity and suitability of his/her own use, handling and disposal of the product. Since actual use by others is beyond our control, no warranty, expressed or implied, is made by Thermoplastic Comfort System, Inc. as to the effects of such use. Thermoplastic Comfort System, Inc. does not assume any liability arising out of use by others of the product referred to herein. The data in this Material Safety Data Sheet relate only to the specific material designated herein and does not relate to use in combination with any other material.